


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 01/97 To (mo./yr.) 01/98
2. DOGM File Number (Mine No): M/041 /008
3. Mine Name: Jensen Quarry
4. Mineral(s) Mined (or permitted to mine): Gypsum
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
 1/4, 1/4, 1/4, Section 22, Township 22S, Range 1W
 1/4, 1/4, 1/4, Section 32, Township 22S, Range 1W
 1/4, 1/4, 1/4, Section 15, Township 22S, Range 1W
7. Name of Operator or Company: United States Gypsum Company
8. Permanent Street Address: Corporate: 125 S Franklin St, Chicago, IL
City, State, Zip: Plant: PO Box 570160, Sigurd, UT 84657 60606-4678
Phone: (435) 896-2400
9. Company Representative (or designated operator):
Name: B.T. Webster
Title: Quarry/Mill Manager
Business Address: PO Box 570160
City, State, Zip: Sigurd, UT 84657
Phone: (435) 896-2450

☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐ ** Jensen Quarry only.
2. If active, how much ore or mineral was mined? 135,867 tons
3. If inactive, what year was the mine last active? _____

3. How much **additional acreage** was disturbed during the past year? 1.69
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
Approximately 68,600 cubic yards of shale and clay were stripped
using a dozer to expose gypsum in the open mining pits.
5. How much acreage was **reclaimed** during the past year? 1.65
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
The reclaimed areas were recontoured using a dozer to push the
overburden spoil piles back into the mined out areas. The
revegetation seed mixture was applied as per the reclamation plan.
No acreage was released from the reclamation program for the year.
7. What is the **total disturbed acreage** at years end? 118.05
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
Mining - Est'd 135,000 tons of gypsum will be mined from existing pits.
Approx. 3 acres will be additionally disturbed during 1998.
Reclamation - Approx. 6 acres are planned to be recontoured and
reseeded as per the reclamation plan during 1998.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.


Name (Typed or Print):

B.T. Webster

Title of Operator:

Quarry/Mill Manager

Signature of Operator:



Date:

01/29/98